

C-O-N-F-I-D-E-N-T-I-A-L

25X1

25X1

| تعت | | |
|-----|---|------------------|
| | C∞O∞N∞F∞I∞D∞E∞N∞T∞I∞A∞L | 25X |
| | ~ 2 ∞ | |
| | | 25X ² |
| | consisted of "ten gums of 15 caliber." embrasures above the turrets. There were antiaircraft gums around the base of the forward mast, one gun of "105 caliber" between the stacks, and one shielded gun at the base of the after mast. The cruiser was equipped with mine releasing gear on both the port and starboard sides. Radar antenna were of the type pictured in the sketch. There were also many "range finders in the form of rods." | 25X |
| 6. | There were two destrovers of from 900 to 1,200 tons in size. They had two guns enclosed in a single mount forward, two single-gun enclosed wounts aft, and two torpedo tubes on each side. | 25X 25X |
| 7. | · | |
| | Port Facilities and Installations | |
| 8. | Pier B in attachment No. 1 designates the place assigned for the loading of tankers. Berths 29 and 30 are assigned only to Soviet ships. Soviet ships have priority in loading over those of other nationalities. Berths 26, 27 and 28 are assigned to ships of other nations. | |
| 9. | The grain elevators which serve berths $1h_0$, 15_0 , and 16 are "capable of supplying 130 tons of cereal an hour to each hold from five troughs." Despite large stocks on hand and the modern equipment, loading is irregular in its time schedule because of the inefficiency of the personnel. Competent and expert operators are not Communist Party members, and so are placed in minor positions. | |
| 10. | Timber is brought to the port in trains and stored in areas indicated by C and D. The pier at C is being enlarged to twice its present capacity. Timber from area C is loaded at berths 24 and 25. Timber is hauled from area D in carts and loaded at berths 11, 12, 13, 16 and 17. | |
| 11. | In the harbor there were a floating dock in which a ship was under construction two dredgers, and a self-propelled shear-leg lighter of 50 to 60 tons. A section of about 50 meters of the pier at berth 19 had collapsed and was being repaired. | 25X |
| 12. | The concrete foundations of a big construction project had been laid in area E. "In the wharf an underground concrete tunnel 1.5 meters high and 8 cm thick is being constructed for office equipment. Its thickness is normal." Along this wharf cranes of 5 to 8 tons capacity are to be installed. | |
| | Civil Affairs, Attitudes, and Reprovise Conditions | |

14. The dock workers and longshoremen were so destitute that they begged for cigarettes. The soldiers and non-commissioned officers in the customs service accept bribes secretly and coincide their visits to the ship

13.

C-O-N-F-I-D-E-N-T-I-A-L


25X1


25X1


| | Approved For Re | ease 2008/05/29 : CIA-RDP80-00 | 810A007500810004-9 | |
|--------------------|--|--|--|-----|
| - 4 5 . | | C=O=N=F=I=D=E=N=T=I=A=L | | 25X |
| | | ∞ 3 ∞ | | |
| | | | | 25X |
| | with mealtime so as to to safety razors. | receive a meal. They asked | for everything from soap | |
| 15. | | are low-spirited and depres | sed; despite their be incapable of the | |
| 16. | Fifty percent of the st items could not be foun expensive. | ores on the main street were d: postcards were not availa | closed down. Luxury | 25X |
| | • ************************************* | | | 25% |
| | | | | |
| | | | | |
| | | | | |
| | | | | 25X |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

CoO-NoF-T-D-F-N-T-T-A-T

25X1







C-O-N-F-I-D-E-N-T-I-A-L 25X1